# Oil Field Environmental Incident Summary

Responsible Party: Nakota Trucking LLC

Well Operator: Tidal Energy Well Name: Trenton Station

Field Name: Well File #:

Date Incident: 6/5/2014 Time Incident: 09:45 Facility ID Number:

County: WILLIAMS Twp: 154 Rng: 102 Sec: 34 Qtr:

Location Description:

Trenton Station Tidal Energy Lot # 2 4807 Highway 1804 Trenton North

Dakota 58853 cord. 4806859N and 103464084W

Submitted By: Manuel Zendejas Received By:

Contact Person: M Drew Gordon

301 58tth St W # 595 Williston , ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 5 Barrels 5 Barrels

**Brine** 

Other

Description of Other Released Contaminant:

No other released Material

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Immediate risk level low - area contained and spill and soiled earth reclaimed

Areal Extent:

Contained area - 20ft x 10ft

## Potential Environmental Impacts:

No impact to environment spill contained and soiled earth recovered and disposed of in accordance to all EPA and State Requirements.

### Action Taken or Planned:

Source of spill immediately closed. Spill was contained with earth dike and absorbent materials, cleanup was accomplished

by contracted recovery team. Contaminated waste will be properly disposed of at State Depository.

Wastes Disposal Location: IHD Solid Waste Management Area 14070 43rd St NW Alexander ND

58831 Pone: 701.774.8514

Agencies Involved: No injury or fire occurred. No other agency was required for recovery efforts

## **Updates**

Date: 6/6/2014 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Five-barrel release of crude oil that is contained and reclaimed, according to spill report. 6/6/14 - 16:50 Phone conversation with Nakota Trucking contact.

Company contact informed me that the release had been contained, and soil was removed and left on location. He also gave me the location as the Trenton LACT units. Manuel Zendejas phone number incorrect on report; should be 501.743.5763. Follow up for more specific coordinates and cleanup observations.

Date: 6/18/2014 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Actual Lat-Long 48.114166 N -103.778206 W

Located at Enbridge Trenton Station

Date: 6/30/2014 Status: Inspection Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Arrived on location 6/24/14.

Site has been cleaned up with no sign of impacted soil other than two piles of impacted soil waiting to be removed.

No follow up is necessary.